

Bt848A

Literature Affected: L848A_A Datasheet

Product Affected: Bt848A

errata sheet

In the parametric information section, Table 22, there are entries with a TBD parameter. This errata sheet contains the correct data for that table.

Parameter	Symbol	Min	Typ	Max	Units
Supply Current	I				
$V_{AA}=V_{DD}=5.0V$, $F_{S2}=28.64$ MHz, $T=25^{\circ}C$		220			mA
$V_{AA}=V_{DD}=5.25V$, $F_{S2}=35.47$ MHz, $T=70^{\circ}C$			294		mA
$V_{AA}=V_{DD}=5.25V$, $F_{S2}=35.47$ MHz, $T=0^{\circ}C$			307		mA
Supply Current, Power Down				65	mA

If you have any questions concerning this erratum, please contact Rockwell Field Application Engineering.



Rockwell

Because
Communication
Matters™